

31651

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 200 No. 56145 Survey held at London Date, first Survey May 19th Last Survey May 31st 1891
on the four masted ship "Otago" Master G. Stuart
Tonnage 993 built at Port Glasgow When built 1869
By whom built Duncan Owners Albion Shipping Coy.
Port belonging to Glasgow Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock Ratcliff (Dry Dock, E.I. Dock)
Last Survey, No. 56145 Port Glasgow Classed 17 A 1
9.69

REPAIRS, &c.

how done,

The metal sheathing stripped, and the bottom caulked and re-sheathed with Yellow metal -

Present Condition of the

Decks	<u>good where seen</u>	Treenails	<u>good where seen</u>	Windlass and Capstan	<u>good and efficient</u>
Waterways		Breasthooks and Stemson		Pumps	
Timings		Transoms, Pointers, and Crutches		Boats <u>five</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>from deck</u>	
Planksheers		Keelsons		Sails	
Deerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. 1 S. 2 K</u>	
Oppsides		Ceiling		Cables	
Rules		Rudder		Hawsers and Warps	
Hulk (Bottom) and Counter		Copper <u>YM</u> When put on <u>now</u>		Standing & Running Rigging	
Engine Room Skylights	<u>✓</u>	Caulking of			
Coal Bunker, Openings, Lids, &c.	<u>✓</u>	Bottom, Deck, & Waterways			
General Observations and Opinion,		Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u>			

She is now in good and efficient condition, fit in my opinion to remain as classed

Amount of Entry Fee.....£ - : - : } is received by me,
Special..... 1 : 1 : }
Certificate (if required) : 5 : }

Committee's Minute 6th June 1891

Character assigned 17 A 1 record Am

17 A 1
J. H. M. M. M.