

To complete Continuation S.S. No 2. 31695  
**REPORT of SURVEY for REPAIRS.**

No. in Reg. Book. **448** No. **31695** Survey held at **London** Date, first Survey **May 27** Last Survey **June 22** 18 **71**  
 on the **"Chrysolite"** Master **J. Aker**  
 Tonnage **471** built at **Aberdeen** When built **1857**  
 By whom built **J. Brodie** Owners **J. Brodie**  
 Port belonging to **London** Destined Voyage **Mauritius**  
 If Surveyed Afloat or in Dry Dock **Princes dock & St. Katharines**  
 Last Survey, No. **31207** Port **Lon** Classed **14 A 5**  
 Cont **65 - 5 - 2.70**  
 IRS, &c.

Also Half Time, on Continuation -

The outside from the waterway seam down to the keel passed by Mr. Pritious, see London Survey No. 31201. The remainder of the hold and air courses examined as per Rule, the outside plank of Seak allowed to remain on application of the Owner a trenail-hole being bored in each timber and all found satisfactory (see Letter), a short plank removed in each buttress and renewed with Seak, broughtree timbers of English Oak, Windlass stripped and chains ransed, see below J.T.O.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Trways	Breasthooks and Stemson	Pumps
ings	Transoms, Pointers, and Crutches	Boats
per Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <i>Except chains</i>
Lower Deck Beams & Fastenings	Ditto Ditto at other places <i>Good</i>	Condition, how ascertained <i>Good</i>
Planksheers <i>Good</i>	Keelsons	Sails <i>14</i>
Sheerstrakes	Clamps and Shelves	Anchors No. of <i>3x1x2</i> <i>sufficient</i>
Upsides	Ceiling	Cables <i>120/ins good</i>
Wales	Rudder	Hawsers and Warps <i>150/ins small</i>
Plank (Bottom) and Counter	Copper <i>E+YML</i> When put on <i>1870</i>	Standing & Running Rigging <i>good</i>
Engine Room Skylights	Caulking of	Cargo and Main Hatchways <i>good</i>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <i>good whatever</i>	Hatches <i>good</i>

General Observations and Opinion,

This vessel having now completed the requirements of the Rules, Section 54 2<sup>nd</sup> part, is eligible in our opinion to be continued *GA* from 1865

The Amount of Entry Fee.....£ 5 : - : - is received by me,

Special..... 4 : 4 : -

Certificate (if required) - : 5 : -

Committee's Minute

Character assigned

*27<sup>th</sup> June 1871*  
*Cont'd 1 for 9 years*  
*from 1865*  
*H.T.71*



©2021

Lloyd's Register Foundation

LON656-0432



31695 Son

Topsides recaulked, Head refastened  
and fore yard renewed -

Thos. W. Wain  
J. J. Wain



© 2021

Lloyd's Register  
Foundation