

REPORT of SURVEY for REPAIRS.

31704

No. in Reg. Book. 887 No. 30770 Survey held at London Date, first Survey 3rd April Last Survey May 16 1871
 on the S. "Asshur" Master Newman
 Tonnage 460 built at Aberdeen When built 1863
 By whom built J Duthie Owners A Hector
 Port belonging to London Destined Voyage Bushill
 If Surveyed Afloat or in Dry Dock Stitch cross dry dock & St Katharines
 Last Survey, No. 30770 Port Lon. Classed 10 A 1
 REPAIRS, &c. (H.T. 68) 4-70

Yellow metal stripped off & caulked from keel to metal line and the yellow metal sheathing renewed on felt -

Present Condition of the

Decks	} <i>Good</i>	Treenails	} <i>Good</i>	Windlass and Capstan	} <i>Good & sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>T & Y M</u> When put on <u>now</u>		Standing & Running Rigging	
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways	Hatches <i>good</i>	

General Observations and Opinion,

This vessel is eligible in my opinion to remain as classed 10 A 1.

Thos. Newman

The Amount of Entry Fee.....£ : : is received by me,

Special..... 1 : 1 : *5*

Certificate (X required) : *5*

Committee's Minute *4th July* 1871

Character assigned *10 A 1 record Y M*



© 2021
Lloyd's Register
Foundation