

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 180 on the Ship **Electra** Survey held at **London** Date, first Survey **14th June** Last Survey **July 7th** 1871.
 Tonnage **668** built at **Aberdeen** When built **1866**
 By whom built **Halker & Co.** Owners **Parker & Co.**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **East India Dock**

Last Survey, No. **31689** Port **Lari** Classed **17. A. 1.**
6.71

REPAIRS, &c.

From damage by collision with the *Gosport*.
 Renew'd the following on the Port side in Midp's viz.
 5 planks of bershiny 20 ft in length $1\frac{1}{8}$ thick.
 1 of 2 ins 20 ft long. $1\frac{1}{2}$ - " -
 Pin rail 36 ft long, 9 ins by 4 ins inside and moulding rail outside
 1 Main Shroud, and some lanyards, fresh seizings & lashings all made good,
 Small gawnpiece let into covering board where chafed and
 the Bulwark Stansions caulked in wake of the above. -

Present Condition of the

Decks	<i>good</i>	Freeboards	<i>good</i>	Windlass and Capstan	<i>good and efficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <i>2, 1, 13, 2, 10, 18.</i>	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <i>Iron & M.K.</i> When put on <i>1871</i>		Standing & Running Rigging	
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers <i>good</i>	Cargo and Main Hatchways <i>good</i>	Hatches <i>good</i>	

General Observations and Opinion,

She is in good condition and Entitled to remain at Class **17. A. 1.**
Samuel Presorius

The Amount of Entry Fee.....£ **2** : - : is received by me,

Special..... **1** : **1** : *14/7/71*

Certificate (if required) : :

Committee's Minute **18th July** 1871

Character assigned **17th July**
second damage repair

Electon

REPORT OF SURVEY FOR REPAIRS



© 2021

Lloyd's Register
Foundation