

21753

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey July 5 Last Survey July 17 1871  
on the Ship "Parramatta" Master J. B. Surman  
Tonnage 1521 built at Sunderland When built 1866-5 M  
By whom built Laird Owners Devitt & Co  
Port belonging to London Destined Voyage Sydney  
If Surveyed Afloat or in Dry Dock Union Dry Dock & Afloat  
Last Survey, No. 29364 Port Lond. Classed 13 A. 1

REPAIRS, &c.

*Stripped off all the yellow metal sheathing. Caulked from keel to metal line. And hulls of topsides reshathed with yellow metal on felt.*

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>When seen good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	<u>Six</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	<u>from Deck</u>
Planksheers	"	Keelsons	"	Sails	<u>Good &amp; Sufficient</u>
Sheerstrakes	"	Clamps and Shelves	"	Anchors	No. of <u>3 B. 1 S. 2 H.</u>
Topsides	"	Ceiling	"	Cables	<u>Good</u>
Wales	"	Rudder	"	Hawsers and Warps	<u>And</u>
Plank (Bottom) and Counter	"	Copper, <u>7 1/2</u> in When put on <u>new</u>	"	Standing & Running Rigging	<u>Sufficient</u>
Engine Room Skylights	"	Caulking of	"	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	<u>Good</u>	Hatches	<u>Good</u>

General Observations and Opinion,

*This vessel is now in good condition. and in my opinion eligible to remain as classed*

The Amount of Entry Fee.....£ — : — : is received by me,

Special.....2 : 2 : 227.72

Certificate (if required) none

Committee's Minute 25<sup>th</sup> July 1871

Character assigned 13 A 1  
second GM



© 2021

Lloyd's Register  
Foundation

LON656-0464