

# REPORT of SURVEY for REPAIRS.

31786

Rec 2/8/71

No. in Reg. Book. **No.** Survey held at London Date, first Survey May 27 Last Survey May 29 1869  
307 on the John Duthie Master Phillips  
 Tonnage 1031 built at Aberdeen When built 1864  
 By whom built Duthie & Son Owners Duthie  
 Port belonging to Aberdeen Destined Voyage London  
 If Surveyed Afloat or in Dry Dock Wigams Dock  
 Last Survey, No. 27692 Port Lon. Classed II A  
 9.86

## REPAIRS, &c.

Vessel in dry dock. Yellow metal sheathing stripped and bottom caulked from keel to height of yellow metal & bottom resheathed with yellow metal on keels.

## Present Condition of the

Decks	Good when seen	Treenails	Good when seen	Windlass and Capstan	Good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper When put on		Standing & Running Rigging	
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways	Hatches	

## General Observations and Opinion,

Being now in good order and condition the opinion that she is eligible to remain as classed II A. Marked in the Book 724-22-1869

The Amount of Entry Fee.....£..... is received by me,

Special.....

Certificate (if required) .....

Committee's Minute 4<sup>th</sup> August 1871

Character assigned III record III

Joseph J. Lister



Lloyd's Register Foundation

LOW 654-0016