

ANNUAL SURVEYS.

31808

No. 98 Survey held at London Date 17th July 1871.
 on the Ship "Vellesley" Master W. B. Green
 Tonnage 983 Built at London When built 1844
 By whom built Green Owners Little & Co
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Green's dry dock

Last Survey, No. 30787 Port of Lon.Classed 12

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Lead</u> When put on <u>1870</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patches Yellow Metal Sheathing
is now in good and efficient condition fit for the
safe conveyance of dry and perishable cargoes to and from
 Committee's Minute 18th August 1871 all parts of the hull and in my
 Character assigned 1 in Red opinion eligible to remain as classed.

J. H. Turner Certificate (if required).

No. 126 Survey held at London Date 14th Aug⁶ 1871.
 on the Ship "Pembrokehire" Master Wilkinson
 Tonnage 721 Built at Pembroke Dock When built Nov. 1 mo
 By whom built Allen Owners Penkins & Co
 Port belonging to London Destined Voyage Pomboy
 If Surveyed Afloat or in Dry Dock Bridge dry dock and afloat

Last Survey, No. 30881 Port of Lon.Classed 10 A

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Lead</u> When put on <u>1870</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

One gar and Mizzen topmast bent of Pine. patches Yellow
Metal Sheathing. is now in good and efficient condition;
 Committee's Minute 18th August 1871 and in my opinion eligible to remain
 Character assigned 1 in Red as classed.

J. H. Turner Certificate (if required).