

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *478* No. *30530* Survey held at *London* Date, first Survey *May 5* Last Survey *June 5* 18 *71*  
on the *S. Anglo Saxon* Master *A Davidson*  
Tonnage *69 3* built at *Sunduland* When built *1854*  
By whom built \_\_\_\_\_ Owners *W. R. Frost*  
Port belonging to *London* Destined Voyage *Sydney*  
If Surveyed Afloat or in Dry Dock *Purves dry dock & London Dock*  
Last Survey, No. *30530* Port *Lon.* Classed *13 A 1*  
*Cont by 9 11.69*

## REPAIRS, &c.

*Yellow metal stripped off; recaulked from keel to metal line also the butts above, and the yellow metal renewed on Selt*

## Present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>Good &amp; sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <i>T &amp; JM</i> When put on <i>new</i>		Standing & Running Rigging	
Engine Room Skylights	Coat Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways	Hatches	<i>good</i>
General Observations and Opinion,	<i>This vessel is eligible in my opinion to remain as classed A 1</i>				

The Amount of Entry Fee.....£ : : is received by me, *Thos. W. Wain*

Special..... 1 : 1 : *W. Wain*

Certificate (if required) : : *W. Wain*

Committee's Minute *22<sup>nd</sup> September* 18 *71*

Character assigned *Cont 9*



© 2021

Lloyd's Register Foundation

LOV 657 - 0079