

REPORT of SURVEY for REPAIRS.

31901

No. in Reg. Book. 243 No. 43 Survey held at London Date, first Survey April 24th Last Survey May 24 1871
 on the "Dorothy" Master J. Williams
 Tonnage 310 built at Gloucester When built 1864
 By whom built _____ Owners James & Co
 Port belonging to Aberystwyth Destined Voyage Sinecorte
 If Surveyed Afloat or in Dry Dock New Crane & South West India Dock

Last Survey, No. 29975 Port Lon. Classed GA 1
 REPAIRS, &c. (HT. 69) 3.69

Yellow metal sheathing stripped off recaulked from keel to metal line and the yellow metal renewed on Felt.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>T&M</u> When put on <u>now</u>	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>good when last</u>	
Scuppers	Cargo and Main Hatchways	Hatches <u>good</u>

General Observations and Opinion,

This vessel appears in good condition and eligible in my opinion to remain as classed

The Amount of Entry Fee.....£ : : is received by me Thos. W. Wain
 Special..... 1 : 1 : : WMC
 Certificate (if required) : 5 : : 29/9/71

Committee's Minute 29th September 1871
 Character assigned GA 1

