

REPORT of SURVEY for REPAIRS.

31919

No. in Reg. Book. 692 No. 1153 Survey held at London Date, first Survey 10 Aug 1871 Last Survey 9 Sept 1871
 on the Ship "Stonehouse" Master C. Pley-
 Tonnage 1153 built at Salerno When built 1866-8 mo
 By whom built Smith & Co Owners J. Morrison
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock in a dry dock and afloat

Last Survey, No. 31185 Port Lon. Classed 13A1
 REPAIRS, &c. cf 9.70

*Caulked flat of upper deck, and patches Lellon Metal
 Sheathing.
 Mizen Mast, Mizen topmast and the Mizen topsail-
 yards here of Pine.*

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>—</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>—</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>—</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>Examined aloft</u>
Planksheers	Keelsons	Sails	<u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>2 Good</u>
Topsides	Ceiling	Cables	<u>and</u>
Wales	Rudder	Hawsers and Warps	<u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>4 1/2 in</u> When put on <u>1870.</u>	Standing & Running Rigging	<u>Good</u>
Engine Room Skylights	Caulking of <u>3 good where</u>	Scuppers	<u>good</u>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>Examined</u>	Cargo and Main Hatchways	<u>good</u>
General Observations and Opinion,		Hatches	<u>good</u>

*Ship in good, and efficient condition, and in
 my opinion eligible to remain as classed.*

The Amount of Entry Fee.....£ — : — : is received by me,

Special.....1 : 1 : 1

Certificate (if required) : 5 : 5

Committee's Minute 6th October 1871

Character assigned 13 A 1

M. Turner

J. D. W.



© 2021

Lloyd's Register
 Foundation

LOW 657-0104