

REPORT of SURVEY for REPAIRS.

31943

No. in Reg. Book. 141 No. 31347 Survey held at London Date, first Survey 25 Sept. Last Survey 10 Dec. 1871
 on the Ship "Cameroon" Master R. Marsden
 Tonnage 1431 built at London When built 1855
 By whom built Green Owners R. H. Green
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Green's dry dock

Last Survey, No. 31347 Port Lon. Classed Rest. 63 - 9 yrs.
"H. T. 69" 1-7!

REPAIRS, &c.

Stripped Yellow Metal sheathing, caulked from keel & gunwale, and resheathed bottom with Yellow Metal on felt.

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>4</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>4</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>4</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>See from Hatches</u>
Planksheers	Keelsons	Sails	<u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>Good</u>
Topsides	Ceiling	Cables	<u>and</u>
Wales	Rudder	Hawsers and Warps	<u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>to the</u> When put on <u>hull</u>	Standing & Running Rigging	
Engine Room Skylights	Caulking of <u>Good where</u>		
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>Stakes.</u>		
General Observations and Opinion,	Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u> Hatches <u>Good</u>		

Is now in good and efficient condition, and in my opinion eligible to remain as classed.

The Amount of Entry Fee.....£ — : — : is received by me,

Special...../ : / : — } Ch. 6. 17/10/71

Certificate (if required) — : 5 : —

Committee's Minute 20th October 1871

Character assigned Rest-9

record P. M.

J. D. W.



© 2021

Lloyd's Register Foundation

LON 654-0122