

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 379 No. 1142 Survey held at London Date, first Survey 23<sup>rd</sup> Dec Last Survey 11<sup>th</sup> Nov 1871  
 on the Ship "Holtspur" Master J. Porteus  
 Tonnage 1142 built at Newcastle When built 1857  
 By whom built Smith Owners Southern Co  
 Port belonging to London Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Re H. Green's dry dock  
 Last Survey, No. 31139 Port Lon. Classed 1341

REPAIRS, &c.

Half yearly Survey held at London in Aug<sup>r</sup> 1867.  
 See Report No 28514 in which is recorded how "Minclars"

Stripped Yellow Metal sheathing, hung in shores  
 caulked from keel to 2<sup>nd</sup> beam within the waterway. Seam  
 and resheathed bottom with Yellow Metal on felt.

Present Condition of the

Decks	Treenails	Windlass and Capstan	Good
Waterways	Breasthooks and Stemson	Pumps	—
Fastenings	Transoms, Pointers, and Crutches	Boats	—
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	—
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	Seen from the deck
Planksheers	Keelsons	Sails	Good
Sheerstrakes	Clamps and Shelves	Anchors No. of	2 Good
Upsides	Ceiling	Cables	2 and
Wales	Rudder	Hawsers and Warps	Sufficient
Stem (Bottom) and Counter	Copper <u>1 1/2</u> When put on <u>now</u>	Standing & Running Rigging	Good
Engine Room Skylights	Caulking of <u>3</u> <u>good when</u>	Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>3</u> <u>tested</u>	Hatches	Good
General Observations and Opinion,	Scuppers <u>good</u>		

In good, and efficient condition, and  
 in my opinion eligible to remain as classed.

*M. Turner*

The Amount of Entry Fee.....£ : : is received by me,

Special...../ : /

Certificate (if required) : :

Committee's Minute 10<sup>th</sup> November 1871

Character assigned Class 9 A 1



© 2021

Lloyd's Register  
 Foundation

LON 657-0144