

REPORT of SURVEY for REPAIRS.

32006

No. in Reg. Book. 465 No. 2985 Survey held at London Date, first Survey 21st Nov^r Last Survey Nov^r 24th 1871
 on the Marque Skiddaw Master Thos. Park 2^d Parkes
 Tonnage 358 built at Workington When built 1852
 By whom built - Owners J. H. Storm
 Port belonging to Whitby Destined Voyage -
 If Surveyed Afloat or in Dry Dock Gun dry dock
 Last Survey, No. 2985 Port Whitby Classed S.S. / 41. / 6. A. 1. in red.
 REPAIRS, &c. See report of survey for damage.

Overhauled her outside, and inside (as far as practicable),
 renewed two short lengths of Ceiling planks, on the Port side
 forward, and cut out some slight defects both sides, and fitted
 gorse pieces where necessary. Gave her a new Cathead, and
 new channel, to the main rigging on the Starboard side. -

Present Condition of the

Decks	<u>good</u>	Treenails	<u>where seen</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	<u>2 1/2". a new Long Boat recom^d.</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	<u>from the deck</u>
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors	<u>No. of 3, 13, 1. S. 2 1/2.</u>
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	<u>efficient</u>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<u>Fe 44 ml</u> When put on <u>1871</u>	"	Standing & Running Rigging	"
Engine Room Skylights	"	Caulking of	<u>good</u>	"	Cargo and Main Hatchways	<u>good</u>
General Observations and Opinion,		Bottom, Deck, & Waterways	<u>good</u>	"	Hatches	<u>good</u>
		Coal Bunker, Openings, Lids, &c.		Scuppers	<u>good</u>	

Survey'd, partly in ballast.
 As far as seen, she is now in good condition. and I am of opinion
 she is entitled to remain as class'd C. A. 1. in red.
Samuel Presious

The Amount of Entry Fee.....£ : - : } is received by me
 See fee charged £1. for damage Survey, - : - : }
 Special..... : - : }
 Certificate (if required) : 5 : }

Committee's Minute 1st December 1871
 Character assigned in red



© 2021

Lloyd's Register
 Foundation

Spedden

REPORT OF SURVEY FOR REPAIRS



© 2021
Lloyd's Register
Foundation