

REPORT of SURVEY for REPAIRS.

32074

No. in Reg. Book. 81 No. 32074 Survey held at London Date, first Survey Jan 3. 8 Last Survey Jan 7 1872
 on the Ship "Patrician" Master F. J. Wilson
 Tonnage 1140 built at Sunderland When built 1859 - 8m
 By whom built Marshall Owners G. Marshall
 Port belonging to London Destined Voyage Melbourne
☒ Surveyed Afloat ☐ in Dry Dock Victoria (Dock)
 Last Survey, No. 32070 Port Lon Classed 13 A 1
 11.71

REPAIRS, &c.

The following renewed in consequence of Damage from Stress of weather - viz:
 The Fore Mast, with Oregon Pine, the lower rigging to all three masts, and the fore and main stays, with galvanized iron wire, and the main rail and topgallant bulwarks on the Starboard side from the gangway to the forecastle; faulted the topsides from the fore part of the fore rigging to the after part of the main rigging on the Starboard side, and the butts on the Port side - The waterways, plank sheers, covering boards and stanchions and two seams of deck inboard on both sides, caulked.

Present Condition of the

Decks	Treenails	Windlass and Capstan	good
Waterways	Breasthooks and Stemson	Pumps	
Comings	Transoms, Pointers, and Crutches	Boats	and
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	efficient
Plank sheers	Keelsons	Sails	
Sheerstrakes	Clamps and Shelves	Anchors No. of	where
Topsides	Ceiling	Cables	
Wales	Rudder	Hawsers and Warps	seen
Plank (Bottom) and Counter	Copper <u>FLYNT</u> When put on <u>1870</u>	Standing & Running Rigging	seen
Engine Room Skylights	Caulking of	Cargo and Main Hatchways	good
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Hatches	good
General Observations and Opinion,	Scuppers		

good where seen
not seen
good where seen
efficient

She has now been put into good and efficient condition, fit in our opinion to remain as classed 13 A 1.

The Amount of Entry Fee.....£ - - - is received by me,

Special.....

Certificate (if required) : 5 :

Committee's Minute 23rd January 1872

Character assigned

Damage Fee 4-4-0

