

REPORT of SURVEY for REPAIRS.

32096

No. in Reg. Book. 677 No. 10794 Survey held at London Date, first Survey 4th April Last Survey 5th April 1871
 on the Ship City of Adelaide Master J. Bruce
 Tonnage 791 built at Swansea When built May - 5th 1864
 By whom built Pile Owners Devitt & Co
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 30794 Port Lon. Classed 14 A 1 S.S. 68
4.70

REPAIRS, &c.

Stripped Yellow Metal Sheathing. Nine planks of deck renewed of 3 $\frac{1}{2}$ Yellow Pine and the greater portion of the poop covering-board of English Oak and Pitch Pine
 faulked from keel to middle of wales as also part of weather-deck and resheathed bottom with Yellow Metal on S&C.

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	<u>4</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>9</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>2</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>See from the deck</u>
Planksheers	Keelsons	Sails	<u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>and</u>
Topsides	Ceiling	Cables	<u>Sufficient</u>
Wales	Rudder	Hawsers and Warps	
Plank (Bottom) and Counter	Copper <u>Good</u> When put on <u>hony</u>	Standing & Running Rigging	
Engine Room Skylights	Caulking of <u>3 good where</u>		
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>3 Cakes</u>		
General Observations and Opinion,	Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u>		

Is now in good and efficient condition, and in my opinion eligible to remain as classed.

The Amount of Entry Fee..... £ 2 : 2 : 0 is received by me,

Special..... £ 2 : 2 : 0

Certificate (if required).....

Committee's Minute 2nd February 1872

Character assigned 14 A 1



© 2021

Lloyd's Register Foundation

LON 651-0233