

REPORT of SURVEY for REPAIRS.

32099

No. in Reg. Book. 234 No. 30509 Survey held at London Date, first Survey 3rd Jan^y Last Survey 23 Jan^y 1872
 on the Composite Ship Eliza Sharr Master J. Gaye
 Tonnage 696 built at Glasgow When built 1863 - 9 mo
 By whom built Stephen Owners C. Sharr
 Port belonging to London Destined Voyage Japan
 If Surveyed Afloat or in Dry Dock Both Green's dry dock and afloat
 Last Survey, No. 30509 Port Lon. Classed 17A1

REPAIRS, &c.

Iron frame planked 5.5.66 11.69
et

The timber boards, one stroke of ceiling in the hold below the upper turn of bilge, one stroke in the flat; together with one other stroke in the tween decks, extending all fore and aft on both sides removed.

Cement coating chipped in parts and found to be sound and good. as also the frames. Plating in way of same. Windows unhung, wood linings stopped and the chain-cables ranged on deck for examination.

Stopped Yellow Metal Sheathing, caulked from keel to upper edge of wales, and resheathed bottom with Yellow Metal on part felt and part paper.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps } <u>Good</u>
Comings	Transoms, Pointers, and Crutches	Boats } <u>Good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>Seen from the deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of } <u>Good</u>
Topsides	Ceiling	Cables } <u>and</u>
Wales	Rudder	Hawsers and Warps } <u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>4 mo</u> When put on <u>1872</u>	Standing & Running Rigging
Engine Room Skylights	Caulking of <u>3 good where</u>	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>3 tests</u>	
General Observations and Opinion, *	Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u>	

Is now in good, and efficient condition, and in my opinion eligible to remain as classed and be marked (5.5.72-72)

The Amount of Entry Fee.....£ : : is received by me,
 Special.....4 : 4 :
 Certificate (if required) : :

Committee's Minute 2nd February 1872
 Character assigned 17A1

32099 Len

Not Supplied

20 fms. ¹⁸/₆ Stanchion. Ketherton Lent 40 Len.

Read Sup^{ts} 20th Jan^r 1872.

Ledge Anchor including stock ^{but. gr. - lbs.} 2 - 3 - 4

W. A. Surves



© 2021

Lloyd's Register
Foundation