

# ANNUAL SURVEYS.

32152

Recd 19/2/72  
1872

No. 332 on the Barque Murtan Survey held at London Date 14<sup>th</sup> Feby  
Tonnage 332 Built at London Master L. Jarvis  
By whom built Salisbury Owners Mullard & Co  
Port belonging to London Destined Voyage Port Natal  
If Surveyed Afloat or in Dry Dock Upper Globe dry dock

Last Survey, No. 31227 Port of Lon. Classed 10. A. 1. c. f  
11. 70

The present Condition of the

Decks <u>good</u>	Treenails <u>where seen</u> <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors, No. of <u>3 B. 1 S. 2 K</u> <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>efficient</u> <u>"</u>	Standing and Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>7 1/2" x 9" mtl</u> When put on <u>1870</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <u>good</u>	

Painted and repaired the Yellow metal.

She is in my opinion entitled to remain as classed 10. A. 1.

Committee's Minute

28<sup>th</sup> Feby 18 72

Character assigned

10 A 1

*[Signature]*

Samuel Presions

Certificate (if required).

100657-0262

Durban  
Chandien



© 2021

Lloyd's Register  
Foundation