

REPORT of SURVEY for REPAIRS.

32222

No. in Reg. Book. *312* No. *1* Survey held at *London* Date, first Survey *March 11* Last Survey *March 12* 18*72*
 on the *Ship Chaa Lze* Master *L Bowen*
 Tonnage *550* built at *Aberdeen* When built *1860-4 M*
 By whom built *Hall* Owners *Devitt & Co*
 Port belonging to *London* Destined Voyage *Adelaide*
 If Surveyed Afloat or in Dry Dock *Union Dry Dock & afloat*
 Last Survey, No. *30801* Port *Lon.* Classed *13 A \ 81 68*
3.70

REPAIRS, &c.

Sighted the bottom, and doubled the yellow metal sheathing from the keel to the light line (13' 6")

Present Condition of the

Decks	<i>Good</i>	Treenails	<i>When seen good</i>	Windlass and Capstan	<i>Good</i>
Waterways		Breasthooks and Stemson	"	Pumps	
Comings		Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	"	Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places	"	Condition, how ascertained	
Planksheers	<i>When</i>	Keelsons	"	Sails	<i>and</i>
Sheerstrakes		Clamps and Shelves	"	Anchors No. of	
Topsides		Ceiling	"	Cables	
Wales		Rudder	"	Hawsers and Warps	
Plank (Bottom) and Counter	<i>Seen</i>	Copper <i>When put on</i>	<i>Good</i>	Standing & Running Rigging	<i>Sufficient</i>
Engine Room Skylights		Caulking of		Cargo and Main Hatchways	<i>Good</i>
Coal Bunker, Openings, Bids, &c.		Bottom, Deck, & Waterways	<i>Good</i>	Hatches	<i>Good</i>
General Observations and Opinion,					

This vessel is now in good condition and in my opinion eligible to remain as classed.

The Amount of Entry Fee.....£ : - : is received by me,

Special...../ : / : }

Certificate (if required) : 5 : }

Committee's Minute *25th March* 18*72*

Character assigned *13 B 1*

J. Lawrence



© 2021

Lloyd's Register Foundation

LON657-0310