

32251

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 482 Survey held at London Date, first Survey Feb 19<sup>th</sup> Last Survey April 2<sup>nd</sup> 1872  
on the S. "Bundaler" Master Ramsay  
Tonnage 921 built at Aberdeen When built 1869 3 ms  
By whom built Humphrey Owners Cannon & Co  
Port belonging to Aberdeen Destined Voyage Adelaide  
If Surveyed Afloat or in Dry Dock Regents dry dock & London Dock  
Last Survey, No. 31480 Port Lon. Classed GA 1 3/1

## REPAIRS, &c.

*yellow metal stripped off, recanted from keel to metal line and the yellow metal sheathing renewed on Selt*

## Present Condition of the

Decks	} <i>Good</i>	Treenails	} <i>Good</i>	Windlass and Capstan	} <i>Sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <i>F &amp; M</i> When put or <i>now</i>		Standing & Running Rigging	
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways	Hatches	<i>good</i>

## General Observations and Opinion,

*This vessel is eligible in my opinion to remain as classed GA 1*

*Thos. W. Traut*

The Amount of Entry Fee.....£ : - : is received by me,

Special..... 1 : 1 : *1/1*

Certificate (if required) : 5 : *5*

Committee's Minute *12<sup>th</sup> April* 18 *72*

Character assigned *GA 1*

*second copy*  
*JJW*



© 2021

Lloyd's Register Foundation

LON657-0328