

REPORT of SURVEY for REPAIRS.

32252

No. in Reg. Book. 381 No. 1 Survey held at London Date, first Survey 22nd Mar. Last Survey 22nd Mar. 1872
 on the Ship "Alumbagh" Master
 Tonnage 1137 built at Sunderland When built 1863 - 5mo
 By whom built Laird Owners Dunbar & Co
 Port belonging to London Destined Voyage India via Cardiff
 If Surveyed Afloat or in Dry Dock in a dry dock
 Last Survey, No. 31540 Port Lon. Classed 13A1

REPAIRS, &c.

(H. Thos - 701)

Stripped Yellow Metal sheathing, hung in shores, caulked from keel to middle of wales, and part of topsides; bottom resheathed with Yellow Metal on felt.

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stenson	Pumps	<u>4</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>4</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>4</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>Seen from the deck</u>
Planksheers	Keelsons	Sails	<u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>Good</u>
Topsides	Ceiling	Cables	<u>and</u>
Wales	Rudder	Hawsers and Warps	<u>Sufficient</u>
Plank (Bottom) and Counter	Coppers <u>4</u> When put on <u>now</u>	Standing & Running Rigging	<u>Good</u>
Engine Room Skylights	Caulking of <u>3</u> <u>Good where tested</u>		
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways		
General Observations and Opinion,	Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u>		

Is now in good, and efficient condition, and in my opinion eligible to remain as classed.

H. Turner

The Amount of Entry Fee.....£ - : - : is received by me,

Special..... : : : H. Turner

Certificate (if required) (: : :)

Committee's Minute 12th April 1872

Character assigned 13A1

record H. Turner

H. Turner



© 2021

Lloyd's Register Foundation

LO 657-0329