

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey 1st May Last Survey 5 June 1872
 on the Ship "York" Master Mernethy
 18. Tonnage 865 built at Sunderland When built 1854
 By whom built _____ Owners J. Allan & Co
 Port belonging to London Destined Voyage Madras
☒ Surveyed Afloat ☐ in Dry Dock Union Dry Dock, Limehouse
 Last Survey, No. 31753 Port Lon. Classed 14 A

REPAIRS, &c.

Yellow Metal Sheathing Stripped, Caulked from Keel to top of Wales, and resheathed with Yellow Metal on Feet -

Main Yard, Fore Yard, & Upper Topsail Yard renewed with Repru, and Red Pine -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>Yell</u> When put on <u>Nov</u>	Standing & Running Rigging
Engine Room Skylights	Caulking of	Hatches
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		

General Observations and Opinion,

Vessel appears to be in good and efficient condition, and eligible in my opinion to remain as Classed -

Henry J. Gyrrell

The Amount of Entry Fee.....£ - : - : is received by me,

Special..... / : / : 0

Certificate (if required) : 5 :

Committee's Minute 21st June 18 72

Character assigned Port 9th



© 2021

Lloyd's Register Foundation