

REPORT of SURVEY for REPAIRS.

32424

No. in Reg. Book. 21 No. 1064 Survey held at London Date, first Survey 6 June Last Survey 11 June 1872
 on the Ship "Palmer castle" Master Waldock Wildash
 Tonnage 1064 built at Sunderland When built 1835
 By whom built Pott Green Owners Pott Green
 Port belonging to London Destined Voyage India via Cardiff
 If Surveyed Afloat or in Dry Dock Pott Green's dry dock and afloat
 Last Survey, No. 31102 Port Lon. Classed 13A1-

REPAIRS, &c.

Painted from metal line to gunwale, and the fore-mast. new of Pine.

It having been notified to the Owners that the "Half-Line Survey" was about due they request the favour of the Ship being allowed to pass on this occasion without the Survey in question being held (she being required for immediate service) they will undertake that the Rules shall be fully carried out on her return.

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stenson	Pumps	<u>Good</u>
Comings	Transoms, Pointers, and Crutches	Boats	<u>Good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	<u>Examined Aloft</u>
Planksheers	Keelsons	Sails	<u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of	<u>Good</u>
Topsides	Ceiling	Cables	<u>Good</u>
Wales	Rudder	Hawsers and Warps	<u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>1m</u> When put on <u>1870</u>	Standing & Running Rigging	<u>Good</u>
Engine Room Skylights	Caulking of <u>Good when</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>Examined</u>	Hatches	<u>Good</u>
General Observations and Opinion,	Scuppers <u>Good</u>		

Is now in good and efficient condition, and in my opinion eligible to remain as classed

M. H. Surner

The Amount of Entry Fee.....£ : - : is received by me,

Special..... : : 5

Certificate (if required) : : 5

Committee's Minute 28th June 1872

Character assigned Port 7.12



© 2021

Lloyd's Register Foundation