

REPORT of SURVEY for REPAIRS.

32477

No. in Reg. Book. **No.** 68 Survey held at London Date, first Survey July 4th Last Survey 1872
 on the S. Saint Vincent Master A. Louthit
 Tonnage 892 built at Sunderland When built 1865-7
 By whom built P. J. & Co. Owners Devitt & Co.
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Union Dry Dock
 Last Survey, No. 31755 Port Lon. Classed 12A SS Lon 71

New 29.77

REPAIRS, &c.

Stripped off all the yellow metal sheathing caulked from keel to metal line, resheathed with yellow metal on paper.

Present Condition of the	Good	Bols.	Good	Good
Decks	Good	Transoms	Good	Windlass and Capstan
Waterways	"	Breasthooks and Stenson	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained
Planksheers	"	Keelsons	"	Sails
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of
Topsides	"	Ceiling	"	Cables
Wales	"	Rudder	"	Hawsers and Warps
Plank (Bottom) and Counter	"	Copper <u>G. M.</u> When put on <u>Now</u>	"	Standing & Running Rigging
Engine Room Skylights	"	Caulking of	"	Hatches
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	Good	Cargo and Main Hatchways
Scuppers	"		"	

General Observations and Opinion, *This vessel is now in good condition and in my opinion eligible to remain as classed.*

Lawrence

The Amount of Entry Fee.....£ : : is received by me,
 Special.....2 : 2 : : MNC
 Certificate (if required) : : 30/7/72

Committee's Minute 2nd August 1872
 Character assigned 12A1

ITW