

REPAIRS, &c.

Present Condition of the

General Observations and Opinion,

The Amount of Entry Fee.....£ 5: 4: 6 is received by me,

Special..... $\mathcal{S} : \mathcal{S} : \mathcal{C}$

Certificate (if required) $\angle : \angle :$

Committee's Minute 20th August 18/2

Character assigned

Cont Δ 1 for 7 Years

From 1868

Ресод реван

32518 Lm

and a pair of diagonal Iron Riders added; all the ceiling from foreward to midships (below the hold beam clamp) new of Pitch Pine - On Starboard Side 3 planks of Wale one of topsides and 3 on buttocks & on port side, 11 of Wale, 1 of topsides and 5 on buttocks of Pitch Pine English and Dantric Oak - Rejuvenated with Australian down to 2 feet below the first futtock heads, caulked from keel to plankheads and reshutted with yellow metal on felt -

Thos. W. Wawn



© 2021

Lloyd's Register
Foundation