

# REPORT of SURVEY for REPAIRS.

32599

No. in Reg. Book. 825 No. 1009 Survey held at London Date, first Survey Aug 26 Last Survey Sept 7 1872  
on the Composite Ship "Mofussilite" Master A. C. Rae  
Tonnage 1009 built at Glasgow When built 1864 qmo.  
By whom built Stephen Owners J. Allan & Sons  
Port belonging to London Destined Voyage Bombay  
If Surveyed Afloat or in Dry Dock Linekiln Dry Dock  
Last Survey, No. 31234 Port Lon. Classed 17 A 1.  
REPAIRS, &c. now done, SS. 69

The bottom caulked and re-sheathed with Yellow Metal upon Felt.

The ceiling in the flat, which is fitted in hatches, lifted, and the tops of the reversed frames painted - the cement found good.

## Present Condition of the

Decks <u>good</u>	Transoms <u>3 m bolts</u> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>where</u>	Ditto Ditto at other places <u>where</u>	Condition, how ascertained <u>where</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 1 S. 2 K</u>
Topsides	Ceiling	Cables <u>seen</u>
Wales <u>seen</u>	Rudder <u>seen</u>	Hawsers and Warps
Plank (Bottom) and Counter <u>caulked</u>	Copper <u>I &amp; Y M</u> When put on <u>now</u>	Standing & Running Rigging
Engine Room Skylights	Caulking of <u>good where</u>	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>tested</u>	
General Observations and Opinion,	Scuppers <u>good</u>	Cargo and Main Hatchways <u>good</u> Hatches <u>good</u>

She is now where seen in good and efficient condition, fit in my opinion to remain as classed 17 A 1.

The Amount of Entry Fee.....£ - : - : is received by me,  
Special..... 1 : 1 :  
Certificate (if required) : 5 :

Committee's Minute 11th October 1872

Character assigned 17 A 1

*Received by me*  
*J. D. W.*



© 2021

Lloyd's Register Foundation