

REPORT of SURVEY for REPAIRS.

32640

No. in Reg. Book. **473** No. **1018** Survey held at **London** Date, first Survey **Sep 12** Last Survey **17 Dec 1842**
on the **Ship "Anglesey"** Master **Brett**

Tonnage **1018** built at **London** When built **1852**

By whom built **Green** Owners **R Green**

Port belonging to **London** Destined Voyage **Port Philip**

If Surveyed Afloat or in Dry Dock **R. & S. Green's Dry Dock & E. I. O.**

Last Survey, No. **31470**

Port **Lon.**

Classed **13 A. 1.**

REPAIRS, &c.

how done

Cont. **65 9. years**

H.T. **70** — **3 m/y**

Placed on blocks in graving dock —
Yellow metal sheathing cleaned and painted,
Wales and portions of Topboards caulked, where
necessary, also Water Seams and Butts of Upper
Deck.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations and Opinion,

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Vessel appears in good condition, and eligible to
remain as classed —

Henry J. Gerrard

The Amount of Entry Fee.....£ — : — : is received by me,

Special..... 1 : 1 : 5/6

Certificate (if required) : : :

Committee's Minute **25th October** 18**42**

Character assigned **Cont 9**



© 2021

Lloyd's Register
Foundation