

Survey with respect to Raised Materials 32736

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey _____ Last Survey 10th Dec^r 1872
 on the Y37. "Alice Holder" Master _____
 Tonnage 200 built at Liverpool When built 1863
 By whom built _____ Owners Brodie & Co
 Port belonging to London Destined Voyage unknown
 If Surveyed Afloat or in Dry Dock Princes dry dock & W. S. Docks
 Last Survey, No. 31600 Port Lon. Classed 7 A 1
Cont Lond. 70. 2

REPAIRS, &c.

a survey having been held on this vessel it was found that the loft timbers were of Red Pine and Oak; viz. 30 Red Pine and 40 Oak on each side, they were all found in good condition having been well salted — also that the White Oak in the sheerstrakes and plank sheers was German Oak which is 8 years material —

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Plank sheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
General Observations and Opinion,	Scuppers	Cargo and Main Hatchways
		Hatches

As the Red Pine loft timbers are still 7 years, I beg most respectfully to leave the matter in the hands of the Committee

The Amount of Entry Fee.....£ — : — : is received by me, Thos. W. Wain
 Special..... 1 : 1 :
 Certificate (if required) — : 5 : paid 20/12/72

Gen Committee's Minute December 10th 1872

Character assigned Raised to 8 A 1 Top Timbers 1st R.P.
Cont 71 — 3 Years

REPORT of SURVEY for REPAIRS.

18

Arouca 6050
Payee Bly No 261



© 2021

Lloyd's Register
Foundation