

No.

Survey held at

London

Date Dec^r 3rd

1872 32748

on the

Ship *Agra*

Master ✓

Tonnage 830

Built at

Liverpool

When built 1858

By whom built

Owners

Johnson &

Port belonging to

Liverpool

Destined Voyage

If Surveyed Afloat or in Dry Dock

Regent dry dock &

Last Survey; No.

31862 Port of *Lon.*

Classed

13. A. 1.
Cont^d 9. A. 1. /41

The present Condition of the

Decks	<i>good</i>	Treenails	<i>good where seen</i>	Windlass and Capstan	<i>in good order</i>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors, No. of	<i>3 13. 15. 20</i>
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder	<i>efficient</i>	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	<i>3 1/4 msl</i> When put on <i>1841.</i>		

General Observations and Opinion.

Caulking of Bottom, Deck, and Waterways

good(Fitted the 4th Metal Plates) - & *weigh'd in Ballast.*

According to the 1st Entry Report the waterways are of Teak, and when she was Cont^d in 71 (See Report) four planks also of Teak were put on aft. - but at present I have not been able to discover that she has any more Teak about her. - The owner however requests that her present character may be submitted with a view to it being raised if appropriate or considered eligible. i.e. to be Cont^d 9. A. 1. from 172

Committee's Minute

24th Dec^r

1872

Gen. Com. Minute

27th Dec^r 1872

Character assigned

13 A. 1. Cont 71 9 Years

Samuel Resins

Certificate (if required).

Gen. Com. to