

32756

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey 22 Nov. Last Survey 16 Dec. 1892
on the Ship "THE T. Ward" Master J. Smith
131. Tonnage 123 1/2 built at Sunderland When built 1862, 5 mo
By whom built Pile Owners R. Green
Port belonging to London Destined Voyage Port Phillip
Surveyed Afloat or in Dry Dock Green's Lower Dock & E. India Dock
Last Survey, No. 32718 Port London Classed 13 H. 1
2 1/2 "H.T." '68"

REPAIRS, &c.

Placed in Dock for examination - Y.M. Sheathing repaired and renailed in places. Butts of braces and Lopers, and portions of buttock beams caulked where necessary - New Kause pipe, fitted on Starboard side - and Mizzen Mast covered with yellow pine.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings <u>Good</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places <u>where</u>	Condition, how ascertained <u>Good and suff.</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shells <u>seen</u>	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder <u>Yell</u> When put on <u>71</u>	Hawsers and Warps
Plank (Bottom) and Counter	Caulking of <u>where</u>	Standing & Running Rigging
Engine Room Skylights	Bottom, Deck, & Waterways <u>where</u>	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	Scuppers	Hatches

General Observations and Opinion,

Vessel appears in good condition and eligible to remain as classed "H. 1"
from Dec. Henry J. Gurnell

The Amount of Entry Fee.....£ - : - : is received by me,

Special.....1 : 1 : of ago

Certificate (if required) : 5 : 11/1/73

Committee's Minute 3rd January 1893

Character assigned 13 A

J.P.M.



© 2021
Lloyd's Register
Foundation
LON658-0129