

33132

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 415 Survey held at London Date, first Survey 10th Apr Last Survey 1st May 1873.
on the Ship "Silver Eagle" Master J. Case
Tonnage 903 built at Leam When built 1861 & new
By whom built _____ Owners Merchant Shipping Co.
Port belonging to London Destined Voyage Sydney.
If Surveyed Afloat or in Dry Dock Canal Dry Dock & London Dock

Recd 8.5.73
Cuth

Last Survey, No. 22068 Port London HT Classed "A 1" 1/42.

REPAIRS, &c. Now Done. Placed on blocks - Yell sheathing stripped
caulked from keel to metal line, and re-sheathed with Y. Metal,
out Paper. Upper Deck caulked, from W. way beams to M. Hatch way.
Windlass renewed with Leam through Spindle, All the Masts
Shortened, and Rigging refitted -

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	<u>Good</u>
Planksheers	"	Keelsons	"	Sails	<u>and</u>
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	<u>Safe</u>
Topsides	"	Ceiling	"	Cables	
Wales	"	Rudder	"	Hawsers and Warps	
Plank (Bottom) and Counter	"	Copper <u>Y.M.</u> When put on <u>Nov.</u>		Standing & Running Rigging	
		Caulking of			
		Bottom, Deck, & Waterways			

Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations and Opinion, This vessel appears to be in good and efficient
condition, and eligible to remain as classed "A 1"

Henry J. Gerrard

The Amount of Entry Fee.....£ _____ is received by me,
Special.....2.2 "0"
Certificate (if required) _____

Committee's Minute 7th July 1873

Character assigned A 1
Recorded
J. D. W.



© 2021
Lloyd's Register
Foundation
LON 658 - 0381