

ANNUAL SURVEYS.

33224

Read 6.8.73

No. 434 Survey held at London Date July 17th 30th 1873
 on the Ship Sir William Wallace Master Colville
 Tonnage 967 Built at Aberdeen When built 1866-1 mo
 By whom built Rushie Owners Tulloch Junr
 Port belonging to Aberdeen Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Regent dry dock & London Docks

Last Survey, No. 3316 Port of London Classed 11. A. 1. 11/7/70

The present Condition of the			
Decks	<u>good</u>	Treenails	<u>good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder <u>efficient</u>	"
Plank (Bottom) and Counter	"	Copper <u>Al & Gmsl</u> When put on	"
		Windlass and Capstan	<u>in good order</u>
		Pumps	"
		Boats	"
		Masts, Yards, &c.	"
		Sails	"
		Anchors, No. of <u>3 B. 13. 2 K</u>	"
		Cables	"
		Hawsers and Warps	"
		Standing and Running Rigging	"

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good
Fitted a new Hold beam abast the Fore hatchway.
Sighted the Yellow metal sheathing and repaired it
She is in good condition, and in my opinion is entitled to remain
 Committee's Minute 12th August 1873. as Class'd 11. A. 1.
 Character assigned 11A Samuel Presius
 Certificate (if required).

No. 280 Survey held at London Date July 25th 30th 1873
 on the Ship Sea Breeze Master J. Harry
 Tonnage 685 Built at Sunderland When built 1856
 By whom built — Owners Blythe & Greene V.L.
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Regent dry dock & S. W. India Docks

Last Survey, No. 20129 Port of London Classed Cont'd 69. 4. A. 1.

The present Condition of the			
Decks	<u>good</u>	Treenails	<u>good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder <u>efficient</u>	"
Plank (Bottom) and Counter	"	Copper <u>Al & Gmsl</u> When put on <u>1872</u>	"
		Windlass and Capstan	<u>in good order</u>
		Pumps	"
		Boats	"
		Masts, Yards, &c. <u>Mizen mast repaired</u>	"
		Sails	"
		Anchors, No. of <u>3 B. 15. 2 K</u>	"
		Cables	"
		Hawsers and Warps	"
		Standing and Running Rigging	"

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good
Sighted the Yellow metal and patched it in places
She is in good condition and in my opinion she is entitled to remain
 Committee's Minute 12th August 1873. as Class'd Cont'd 69. 4. A. 1.
 Character assigned Cont'd 4. A. 1. Samuel Presius
 Certificate (if required).

Gen William Wallcut
Lee Breezy



© 2021

Lloyd's Register
Foundation