

ANNUAL SURVEYS.

33449

No. 157 Survey held at London Date 13th Oct. Nov 7th 1873
 on the Barque Vimeira Master J. H. Greston
 Tonnage 941 Built at Sunderland When built 1851
 By whom built — Owners J & K. Grant
 Port belonging to London Destined Voyage Negapatam
 If Surveyed Afloat or in Dry Dock Repent dry dock & S.W. India docks.

Last Survey, No. 32342 Port of London Classed Cons^d 9.A.1. / 65
 HT68 5.32

The present Condition of the

Decks	good	Treenails	where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of	3 B. 15. 2 W
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder	efficient	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	5 1/2 m th When put on	1872		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Survey'd with part Cargo on board. Sighted, patched, and repaired the Yellow Metal. Rebolled the fore Channel. Made good the Steering wheel. Rigging part renewed and put in order. — She is in good condition and in my opinion is entitled to remain as classed 9.A.1.

Committee's Minute 7th Nov. 1873

Character assigned Cons^d 9.A.1.

Certificate (if required).

J.H.W.

Samuel P. Jones

No. 151 Survey held at London Date 14th Oct. Nov 7th 1873
 on the Barque Jane Fairlie Master Wm Harris
 Tonnage 361 Built at Scilly When built 1872 - built
 By whom built Fairlie Owners M. Laren
 Port belonging to Greenock Destined Voyage Greenock
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 290 Port of Scilly Classed 13.A.1.
 6.52

The present Condition of the

Decks	good	Treenails	where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of	3 B. 15. 2 W
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder	efficient	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	5 1/2 m th When put on	1872		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Sighted the Yellow Metal. — She is now in good condition and in my opinion is entitled to remain as classed 13.A.1.

Committee's Minute 7th Nov. 1873

Character assigned 13.A.1.

Certificate (if required).

J.H.W.

Samuel P. Jones

Wm. H. H. H. H.
Lane H. H. H.



© 2021

Lloyd's Register
Foundation