

33570

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.
131

No.

Survey held at

London

Date, first Survey

28th Aug

Last Survey

16th Apr 1874

on the

P. Cardiganshire

Master

M. Bracken

Tonnage

365

built at

Weyland

When built

1864

By whom built

Lagdon

Owners

P. Pentins

Port belonging to

London

Destined Voyage

Not known

If Surveyed Afloat or in Dry Dock

Bridge Dry Dock & Afloat

Last Survey, No.

31873

Port

London

Classed

14 A 1

REPAIRS, &c.

None done.

H.T. 40. 9. 41

The yellow metal sheathing stripped off the bottom and elsewhere. Caulked from keel to metal line, and resheathed with Y.M. on felt. Mizen mast now of pitch pine. Rigging repaired.

Present Condition of the

Decks

Good

Waterways

do

Comings

do

Upper Deck Beams & Fastenings

do

Lower Deck Beams & Fastenings

do

Planksheers

do

Sheerstrakes

do

Topsides

do

Wales

do

Plank (Bottom) and Counter

do

Treenails

When seen good

Breasthooks and Stemson

do

Transoms, Pointers, and Crutches

do

Timbers of the Frame at the openings

do

Ditto Ditto at other places

do

Keelsons

do

Clamps and Shelves

do

Ceiling

do

Rudder

do

Copper

Y.M. When put on

do

Caulking of

Good

Bottom, Deck, & Waterways

Good

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

Good

General Observations and Opinion,

She is in good Condition, fit for the safe conveyance of dry and perishable Cargoes to and from all parts of the World, and is in my opinion eligible to remain as classed

The Amount of Entry Fee.....£

is received by me,

Special.....

Certificate (if required).....

Committee's Minute

13th January 1874

Character assigned

14 A 1

Received by me
J. B. W.



© 2021

Lloyd's Register
Foundation

LON659-0127