

33649

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 317 No. 1074 Survey held at London Date, first Survey 5th February Last Survey 16th February 874
on the Ship "Hindor Castle" Master Harrison
Tonnage 1074 built at Sunderland When built 1857
By whom built _____ Owners H. & H. Green
Port belonging to London Destined Voyage Melbourne
If Surveyed Afloat or in Dry Dock Dry Dock and East India Dock
Last Survey, No. 32685 Port London Classed (Feb. 7 - Lon. - 9 yrs) 11/72

REPAIRS, &c.

Sighted the Bottom, and patched the yellow Metal sheathing. - Caulked the Wals above the metal line - also the butts of Topsides. Renewed the Main piece of Rudder with British Oak. -

Present Condition of the		
Decks		Treenails
Waterways	Good	Breasthooks and Stemson
Comings		Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings	Good	Timbers of the Frame at the openings
Lower Deck Beams & Fastenings		Ditto Ditto at other places
Planksheers		Keelsons
Sheerstrakes	Good	Clamps and Shelves
Topsides		Ceiling
Wales		Rudder
Plank (Bottom) and Counter	Good	Copper
Engine Room Skylights	-	When put on
Coal Bunker, Openings, Lids, &c.	-	Caulking of
General Observations and Opinion,		Bottom, Deck, & Waterways
		Scuppers
		Windlass and Capstan
		Pumps
		Boats
		Masts, Yards, &c.
		Condition, how ascertained
		Sails
		Anchors
		Cables
		Hawsers and Warps
		Standing & Running Rigging
		Cargo and Main Hatchways
		Hatches

She is now in good and efficient condition, and fit, in our opinion, to remain classed for nine years from 1891.

The Amount of Entry Fee.....£ : : is received by me,
Special..... 1 : 1 : 0
Certificate (if required) : 5 :
Committee's Minute 24th March 1891
Character assigned Good