

REPORT of SURVEY for REPAIRS.

33779

No. in Reg. Book. **No.** 184 Survey held at London Date, first Survey 18th April Last Survey April 24th 1874
 on the Compt. Barque Berlean Master J. Wyrell
 Tonnage 526 built at Sunderland When built 1869 - snow
 By whom built Pile Owners J. B. Walker
 Port belonging to London Destined Voyage Launceston
 If Surveyed Afloat or in Dry Dock Union dry dock & J. W. India docks.
 Last Survey, No. 22024 Port London Classed Y.A.V.
 REPAIRS, &c. Composite Ship 5.33

*Stripped off the Yellow Metal Sheathing
 Overhauled the Caulking of butts and seams in the bottom
 Resteathed with Yellow Metal on felt. -*

Present Condition of the

Decks	<i>good</i>	Treenails	<i>good</i>	Windlass and Capstan	<i>in good order</i>
Waterways	<i>✓</i>	Breasthooks and Stemson	<i>✓</i>	Pumps	<i>✓</i>
Comings	<i>✓</i>	Transoms, Pointers, and Crutches	<i>✓</i>	Boats	<i>✓</i>
Upper Deck Beams & Fastenings	<i>✓</i>	Timbers of the Frame at the openings	<i>✓</i>	Masts, Yards, &c.	<i>✓</i>
Lower Deck Beams & Fastenings	<i>✓</i>	Ditto Ditto at other places	<i>✓</i>	Condition, how ascertained	<i>from the deck</i>
Planksheers	<i>✓</i>	Keelsons	<i>✓</i>	Sails	<i>✓</i>
Sheerstrakes	<i>✓</i>	Clamps and Shelves	<i>✓</i>	Anchors	No. of <i>3 B. 1 B. 2 K</i>
Topsides	<i>✓</i>	Ceiling	<i>✓</i>	Cables	<i>✓</i>
Wales	<i>✓</i>	Rudder	<i>efficient</i>	Hawsers and Warps	<i>✓</i>
Plank (Bottom) and Counter	<i>✓</i>	Copper	<i>For 4 yrs</i>	Standing & Running Rigging	<i>✓</i>
Engine Room Skylights	<i>✓</i>	Caulking of	<i>good</i>	Cargo and Main Hatchways	<i>good</i>
Coal Bunker, Openings, Lids, &c.	<i>✓</i>	Bottom, Deck, & Waterways	<i>good</i>	Hatches	<i>good</i>
General Observations and Opinion,					

*She is in good and efficient condition, and I am of opinion is
 entitled to remain as Class'd Y.A.V.
 Samuel Prescotes*

The Amount of Entry Fee.....£ 2 : 2 : 0 is received by me,
 Special.....
 Certificate (if required).....

Committee's Minute 12th May 1874
 Character assigned Y.A.V.
J. D. W.



© 2021
 Lloyd's Register
 Foundation

Bureau



© 2021

Lloyd's Register
Foundation