

324158


REPORT of SURVEY for REPAIRS, &c.

in Book. **No.** 541 Survey held at London Date, first Survey 6th May Last Survey 1874
on the Sloop "Prince Rupert" Master A. Bishop
Tonnage 491 built at Pallion When built 1865 (3 Mo.)
By whom built Briggs Owners Hudson's Bay Company.
Port belonging to London. Destined Voyage not fixed
If Surveyed Afloat or in Dry Dock Messrs Dignam's Dry Dock.
Last Survey, No. 32440 Port London Classified 13 Years assigned. A. I. Character in Register Book. 6/92.

REPAIRS, OR EXAMINATION AS PER RULE
Work done: The vessel placed in dry dock, and the keel and bottom examined and found in good condition. The hull of the bottom, the keel seams and hood end have been caulked.

Present Condition of the			
Decks		Treenails	Windlass and Capstan
Waterways	} <u>Good.</u>	Breasthooks and Stemson	Pumps
Comings		Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings		Ditto Ditto at other places	Condition, how ascertained
Planksheers		Keelsons	Sails
Sheerstrakes		Clamps and Shelves	Anchors No. of
Topsides		Ceiling	Cables
Wales		Rudder	Hawsers and Warps
Plank (Bottom) and Counter	} <u>Good.</u>	Copper <u>single bottom</u> When put on	Standing & Running Rigging
Engine Room Skylights			Caulking of
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	
General Observations, Opinion as to Class, &c.		Scuppers	Cargo and Main Hatchways
			Hatches

This vessel is at present laying up in the West India Dock. Capt. D. Herd informs me that the Owners are at present undecided as to the future disposition of her, therefore nothing is being done. Mr. J. Williamson who saw her in dry dock, and wrote the above report, informed the Owners that Half-time Survey was now due.

The Amount of Entry Fee£ : : received by me, }
Special£ . : : 187 }
Certificate (if required)£ : :
(Travelling Expenses, if any, £)
Committee's Minute 13th October 1874
Character assigned _____
Deposited
21/10/74
J. D. W.
 © 2021 Lloyd's Register Foundation
LON660-0007