

ANNUAL SURVEYS.

34205

No. in Reg. Book. 203 No. 192 Survey held at London Date, first Survey 28th Feb^r Last Survey 13th Oct^r 1874
 on the Sch^r Geraldine Master Robt Fleury
 Tonnage 192 Built at Guernsey When built 1871 12 mo.
 By whom built Hadfield Owners Lomas Weston & Co.
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Union dry dock & W. India docks.

Last Survey, No. 33865 Port of London Classed 11.A.1. Years assigned. 2.74 Character in Register Book.
 Present Condition of the Decks good Treenails where seen good
 Waterways 1 Breasthooks and Stemson 1
 Comings 1 Transoms, Pointers, and Crutches 1
 Upper Deck Beams & Fastenings 1 Timbers of the Frame at the Openings 1
 Lower Deck Beams & Fastenings 1 Ditto ditto at other places 1
 Planksheers 1 Keelsons 1
 Sheerstrakes 1 Clamps and Shelves 1
 Topsides 1 Ceiling 1
 Wales 1 Rudder efficient
 Plank (Bottom) and Counter 1 Copper or Y.M. 1874 metal When put on 1874
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights 1 Coal Bunker, Openings, Lids, &c. 1 Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Caulked Topsides, patched the yellow metal sheathing.

Committee's Minute 27th October 1874 Samuel Presious H.A.I.
 Character assigned 11.A.1. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. in Reg. Book. 543 No. 732 Survey held at London Date, first Survey 2nd Oct^r Last Survey Oct^r 13th 1874
 on the Ship Shannon Master R. Harvey
 Tonnage 825 Built at Sunderland When built 1853
 By whom built 1825 Owners Blyth & Greene
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Union dry dock & S. W. India docks.

Last Survey, No. 33533 Port of London Classed Rest 71-5 yrs Years assigned. 12.73 Character in Register Book.
 Present Condition of the Decks good Treenails where seen good
 Waterways 1 Breasthooks and Stemson 1
 Comings 1 Transoms, Pointers, and Crutches 1
 Upper Deck Beams & Fastenings 1 Timbers of the Frame at the Openings 1
 Lower Deck Beams & Fastenings 1 Ditto ditto at other places 1
 Planksheers 1 Keelsons 1
 Sheerstrakes 1 Clamps and Shelves 1
 Topsides 1 Ceiling 1
 Wales 1 Rudder efficient
 Plank (Bottom) and Counter 1 Copper or Y.M. 1874 metal When put on 1874
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights 1 Coal Bunker, Openings, Lids, &c. 1 Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Sighted the yellow metal. and repaired it where required or necessary.

Committee's Minute 27th October 1874 Samuel Presious H.A.I.
 Character assigned Rest 5.A.1. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18