

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at *London* Date, first Survey *13.5.75* Last Survey *May 12 1875*

510 on the *S. Tyburnia*

TONNAGE under Tonnage Deck *862*
Ditto of Spar Deck, or Awning Deck
Ditto of Poop, or Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage *1012*
Crew Space, as per Rule
Register Tonnage, out on Beam
Engine Room *948*
Reg. Tons as St' mer, out on Bm.

Master *Goldar*
Built at *Glasgow* When built *1857*
Owners *Merchant Ship Co* Port belonging to *London*
Residence
By whom built
Destined Voyage *Lyons*
If Surveyed Afloat or in Dry Dock *Dry Dock*

Length of Poop *58 1/2* ft. Ditto, Forecastle *42* ft. Ditto, Raised Quarter Deck *17* ft. Years assigned. *15A1 674* Character in Register Book.

Last Survey, No. *339 144* Port *London* Classed *15A1 674*
REPAIRS, OR EXAMINATION AS PER RULE

At the present time the vessel placed in dry dock, the yellow metal stripped off. Caulked from keel to top of Wales & Waterways. Re yellow metal on felt to near top of Wales.

Cause of Repairs to be clearly stated.

Present Condition of the				
Decks	<i>Good</i>	Treenails	<i>Good</i>	Windlass and Capstan
Waterways	<i>do</i>	Breasthooks and Stemson	<i>do</i>	Pumps
Comings	<i>do</i>	Transoms, Pointers, and Crutches	<i>do</i>	Boats
Upper Deck Beams & Fastenings	<i>do</i>	Timbers of the Frame at the openings	<i>do</i>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	<i>do</i>	Ditto Ditto at other places	<i>do</i>	Condition, how ascertained
Planksheers	<i>do</i>	Keelsons	<i>do</i>	Sails
Sheerstrakes	<i>do</i>	Clamps and Shelves	<i>do</i>	Anchors No. of <i>3</i>
Topsides	<i>do</i>	Ceiling	<i>do</i>	Cables
Wales	<i>do</i>	Rudder	<i>do</i>	Hawsters and Warps
Plank (Bottom) and Counter	<i>do</i>	Copper <i>of Metal</i> When put on <i>on felt to near top of Wales</i>	<i>new</i>	Standing & Running Rigging
Engine Room Skylights	<i>do</i>	Caulking of	<i>do</i>	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	<i>do</i>	Bottom, Deck, & Waterways	<i>do</i>	Hatches
Scuppers	<i>do</i>		<i>do</i>	

General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and in my opinion entitled to remain as classed.

Leahurst Martindale

The Amount of Entry Fee ... £ ...
Special ... £ *2 : 2* ...
Certificate (if required) ... £ ...
(Travelling Expenses, if any, £ ...)

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *21st May 1875*

Character assigned

Class 10A1

Ym 75



© 2021

Lloyd's Register Foundation