

ANNUAL SURVEYS.

34703 37, 520

Recd 20.5.75

No. in Reg. Book. **121** No. **33859** Survey held at London Date, first Survey _____ Last Survey May 19th 1875
 on the S Kinfauns Castle (Compton) Master Kidd
 Tonnage 121 Tonnage 121 Built at Glasgow When built 1867 10M.
 By whom built Cornell Owners J Skinner
 Port belonging to Glasgow Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock By Dock
 Last Survey, No. 33859 Port of London Classed 15A1 6.74
SS Lon 74

Present Condition of the		Treenails		Character in Register Book.		
Decks	<u>Good</u>	<u>Good</u>	<u>Good</u>	Years assigned.	Character in Register Book.	
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	} <u>Good</u>	} <u>and</u>	
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>			
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>			
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>			
Planksheers	<u>do</u>	Keelsons	<u>do</u>			
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>			
Topsides	<u>do</u>	Ceiling	<u>do</u>			
Wales	<u>do</u>	Rudder	<u>do</u>			
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M.	When put on <u>1874</u>			
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>Patched new</u>			
Coal Bunker, Openings, Lids, &c.	<u>do</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>	
General Observations, Opinion as to Class, &c.					Hatches	<u>Good</u>

She is now in an efficient state of repair and in my opinion entitled to remain as classed

Committee's Minute 28th May 1875 15A1
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. **299** No. **32001** Survey held at London Date, first Survey _____ Last Survey May 8th 1875
 on the BK Flying Fish Master Sim
 Tonnage 299 Tonnage 299 Built at Sunderland When built 1858
 By whom built _____ Owners Scrutton & Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock
 Last Survey, No. 32001 Port of London Classed 13A1 7.74
Coal Lon 71-170

Present Condition of the		Treenails		Character in Register Book.		
Decks	<u>Good</u>	<u>Good</u>	<u>Good</u>	Years assigned.	Character in Register Book.	
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	} <u>Good</u>	} <u>and</u>	
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>			
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>			
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>			
Planksheers	<u>do</u>	Keelsons	<u>do</u>			
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>			
Topsides	<u>do</u>	Ceiling	<u>do</u>			
Wales	<u>do</u>	Rudder	<u>do</u>			
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M.	When put on <u>1872</u>			
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>Patched new</u>			
Coal Bunkers, Openings, Lids, &c.	<u>do</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>	
General Observations, Opinion as to Class, &c.					Hatches	<u>Good</u>

She is now in an efficient state of repair and in my opinion entitled to remain as classed

Committee's Minute 28th May 1875 13A1
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

