

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at London Date, first Survey June 5 1875 Last Survey June 5 1875

43 on the Black Ocean Nymph

Master J Macpherson

Official Number
TONNAGE under Tonnage Deck 263.91
Ditto of Spar Deck, or Awning Deck
Ditto of Poop, or Raised Quarter Deck 37.91
Ditto of Houses on Deck
Ditto of Forecastle 9.75
Gross Tonnage 309.77
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St' mer, cut on Bm.

Built at Quebec

When built 1862 YEAR. MONTH. 8

Owners Hudson Bay Co Port belonging to London

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock Dry Dock

Length of Poop to Post 30 1/2 ft. Ditto, Forecastle Monkey ft. Ditto, Raised Quarter Deck 1 ft. Years assigned. 8 A Character in Register Book. 6.74

Last Survey, No. 33896 Port London

REPAIRS, OR EXAMINATION AS PER RULE

Classed 8 A 6.74
Count down from 7 5 years
8.8 down 7.5 years

At the present time the vessel placed in
Dry Dock & caulked from keel to gunwale, also the
Waterways & Decks. owing to damage one short plank
shipped on the Port Bow with Patch Pine
Length as per Register 118.1
Breadth 27.3
Depth 12.6

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u> <u>and</u> <u>sufficient</u> <u>where</u> <u>they could</u> <u>be seen</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Pumps	
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the openings	<u>do</u>	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>do</u>	Ditto Ditto at other places	<u>do</u>	Condition, how ascertained	
Planksheers	<u>do</u>	Keelsons	<u>do</u>	Sails	
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>	Anchors No. of <u>3</u> <u>12 1/2</u> <u>12 1/2</u>	
Topsides	<u>do</u>	Ceiling	<u>do</u>	Cables	
Wales	<u>do</u>	Rudder	<u>do</u>	Hawsers and Warps	
Plank (Bottom) and Counter	<u>do</u>	Copper	<u>do</u>	Standing & Running Rigging	
Engine Room Skylights	<u>do</u>	Caulking of			
Coal Bunker, Openings, Lids, &c.	<u>do</u>	Bottom, Deck, & Waterways	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Scuppers	<u>Good</u>			Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair
and entitled to remain as classed

Senhouse Martin

The Amount of Entry Fee ... £ ... received by me, Harvey
Special ... £ 2 : 2 : ... 14.6.1875


Certificate (if required) ... £ ...

(Travelling Expenses, if any, £)

Committee's Minute 15th June 1875

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation