

ANNUAL SURVEYS.

34881

No. in Reg. Book. on the 1002 No. 60 Survey held at London Date, first Survey 29th July Last Survey 4th Aug 1875
Sr. "Concord" Master J. Lordiner
 Tonnage 168 Built at Peterhead When built 1865 - 1 mo.
 By whom built Gracie Owners Scott & Co.
 Port belonging to Peterhead Destined Voyage Harvie
 If Surveyed Afloat or in Dry Dock Grid Iron Fountain Dock

Last Survey, No. 2675 Port of Aberdeen Classed 8 Years assigned A.1. Character in Register Book.
 Present Condition of the Deck Good Treennails Good where seen Coat Pet Jan 73 580. 5.73.
 Waterways --- Breasthooks and Stenson Good
 Comings --- Transoms, Pointers, and Crutches --- Windlass and Capstan Good
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings --- Pumps 2 like
 Lower Deck Beams & Fastenings --- Ditto ditto at other places --- Boats 2 -
 Planksheers --- Keelsons --- Masts, Yards, &c. ---
 Sheerstrakes --- Clamps and Shelves --- Condition, how ascertained From deck.
 Topsides --- Ceiling --- Sails 2 Suits Good
 Wales --- Rudder Good and efficient Anchors, No. of 2 B. 1 S. 1 K.
 Plank (Bottom) and Counter --- Copper or Y.M. on felt When put on 1873 Cables Good and Sufficient
 Engine Room Skylights --- Caulking of Bottom, Deck, & Waterways Good Hawers and Warps Good and Sufficient
 General Observations, Opinion as to Class, &c. Now done. Patched the yellow metal sheathing, rebolted the chain stoppers, cat tails and quarter piece, repaired the latches and bulwarks, unhooked the windlass and adjusted the spindle.
This vessel is now in good condition and eligible in my opinion to remain as classed.
 Committee's Minute 13th August 1875 J. H. Minnette
 Character assigned Col. D. A. 1 J. H. Minnette Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) --- Paid --- 18

No. 240 Survey held at London Date, first Survey 30th July Last Survey 30th July 1875
 No. in Reg. Book. on the 240 Three masked Br. Thomas, C. Seed Master W. Anderson
 Tonnage 296 Built at Sunderland When built 1873 - 12 mo.
 By whom built Pickersgill Owners T. Seed.
 Port belonging to Fleetw'd Destined Voyage Port Natal
 If Surveyed Afloat or in Dry Dock Grid Iron Gun Dock.

Last Survey, No. 10449 Port of Sunderland Classed 12 Years assigned A.1. Character in Register Book.
 Present Condition of the Deck Good Treennails Good where seen. 12.73
 Waterways --- Breasthooks and Stenson Good
 Comings --- Transoms, Pointers, and Crutches --- Windlass and Capstan Good
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings --- Pumps 2 like
 Lower Deck Beams & Fastenings --- Ditto ditto at other places --- Boats 2 -
 Planksheers --- Keelsons --- Masts, Yards, &c. ---
 Sheerstrakes --- Clamps and Shelves --- Condition, how ascertained From deck.
 Topsides --- Ceiling --- Sails 2 Suits Good
 Wales --- Rudder Good and efficient Anchors, No. of 3 B. 1 S. 2 K.
 Plank (Bottom) and Counter --- Copper or Y.M. on felt When put on 1873 Cables Good and Sufficient
 Engine Room Skylights --- Caulking of Bottom, Deck, & Waterways Good Hawers and Warps Good and Sufficient
 General Observations, Opinion as to Class, &c. Now done. Standing and Running Rigging Sufficient

Patched the yellow metal sheathing -
This vessel is now in good condition and eligible in my opinion to remain as classed.
 Committee's Minute 13th August 1875 J. H. Minnette
 Character assigned 112 A. 1 J. H. Minnette Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) --- Paid --- 18