

ANNUAL SURVEYS.

34900

Recd 16.8.75.

No. in Reg. Book. on the **No.** 56 Survey held at London Date, first Survey 31st July Last Survey 13th Aug^t 1875
Comp^{te} Bk "Ocean Rover" Master G. Dickinson
 Tonnage 548 Built at Sunderland When built 1867 - 7 mo.
 By whom built Thomson Owners Thompson & Co.
 Port belonging to Sunderland Destined Voyage (not fixed)
 If Surveyed Afloat or in Dry Dock In dry dock and afloat.

Last Survey, No. 33330 Port of London

Classed 16 Years assigned 16 Character in Register Book A.I. CP.
S.B. Lon 72.
9.73.

Present Condition of the Decks	<u>good</u>	<u>S. Boats.</u>	<u>where seen good</u>
Waterways	—	Treenails	—
Comings	—	Breasthooks and Stemson	—
Upper Deck Beams & Fastenings	—	Transoms, Pointers, and Crutches	—
Lower Deck Beams & Fastenings	—	Timbers of the Frame at the Openings	—
Planksheers	—	Ditto ditto at other places	—
Sheerstrakes	—	Keelsons	—
Topsides	—	Clamps and Shelves	—
Wales	—	Ceiling	—
Plank (Bottom) and Counter	—	Rudder	<u>good and efficient</u>
Engine Room Skylights	—	Copper or Y.M. on <u>F.</u> When put on <u>173</u>	
Coal Bunker, Openings, Lids, &c.	—	Caulking of Bottom, Deck, & Waterways	<u>good</u>
General Observations, Opinion as to Class, &c.	<u>now done:-</u>		

Patched the yellow metal sheathing, renewed seven brace and pintle bolts, renewed the mizen mast and the main top-gall^t mast also the topgall^t backstays -
This vessel is now in good condition and in my opinion eligible to remain as classed.

Committee's Minute 20th August 1875

Character assigned 16A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. in Reg. Book. on the **No.** 56 Survey held at London Date, first Survey 31st July Last Survey 13th Aug^t 1875
Comp^{te} Bk "Ocean Rover" Master G. Dickinson
 Tonnage 548 Built at Sunderland When built 1867 - 7 mo.
 By whom built Thomson Owners Thompson & Co.
 Port belonging to Sunderland Destined Voyage (not fixed)
 If Surveyed Afloat or in Dry Dock In dry dock and afloat.

Last Survey, No. 33330 Port of London

Classed 16 Years assigned 16 Character in Register Book A.I. CP.

Present Condition of the Decks	<u>good</u>	<u>S. Boats.</u>	<u>where seen good</u>
Waterways	—	Treenails	—
Comings	—	Breasthooks and Stemson	—
Upper Deck Beams & Fastenings	—	Transoms, Pointers, and Crutches	—
Lower Deck Beams & Fastenings	—	Timbers of the Frame at the Openings	—
Planksheers	—	Ditto ditto at other places	—
Sheerstrakes	—	Keelsons	—
Topsides	—	Clamps and Shelves	—
Wales	—	Ceiling	—
Plank (Bottom) and Counter	—	Rudder	<u>good and efficient</u>
Engine Room Skylights	—	Copper or Y.M. on <u>F.</u> When put on <u>173</u>	
Coal Bunkers, Openings, Lids, &c.	—	Caulking of Bottom, Deck, & Waterways	<u>good</u>
General Observations, Opinion as to Class, &c.	<u>now done:-</u>		

Committee's Minute 20th August 1875

Character assigned 16A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18