

# REPORT of SURVEY for REPAIRS, &c.

\*33061

Red 8-9-75

No. in Reg. Book. **No.** 130 on the **Bk "Vicar of Bray"** Survey held at **London** Date, first Survey **20 July** Last Survey **23 July** 18**75** Master **J. Hallenau**

**TONNAGE** under Tonnage Deck **365** Built at **Whitehaven** When built **1841**  
 Ditto of Spar Deck, or Aching Deck  
 Ditto of Poop, or Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as St'mer, cut on Bm.

Owners **Ralkland & Co** Port belonging to **London**  
 Residence  
 By whom built  
 Destined Voyage **Ralkland Isld**  
 If Surveyed Afloat or in Dry Dock **Sketchers dry dock & afloat**

Length of Poop **29.82** ft. Ditto, Forecastle **12.91** ft. Ditto, Raised Quarter Deck **12.91** ft.  
 Last Survey, No. **2982** Port **Bristol** Classed **12 A1** Ret 59-8 Cont 105 Expired 3. 68

REPAIRS, OR EXAMINATION AS PER RULE  
 Request made for survey with the object of reclassification but subsequently declined. Vessel not prepared for examination.

Yellow metal sheathing now stripped off. Several stakes of Deck renewed on each side and the Beams thus exposed good. Caulked from keel over all the bottom & sheathed with Yellow metal on felt.

Wm. C. Dancy  
 Thos. C. Concedo

Present Condition of the  
 Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Berstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter  
 Engine Room Skylights  
 Coal Bunker, Openings, Lids, &c.  
 Scuppers  
 Cargo and Main Hatchways  
 Hatches  
 General Observations, Opinion as to Class, &c.

Treenails  
 Breasthooks and Stenson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the openings  
 Ditto Ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper  
 When put on  
 Caulking of  
 Bottom, Deck, & Waterways

Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Condition, how ascertained  
 Sails  
 Anchors No. of  
 Cables  
 Hawsers and Warps  
 Standing & Running Rigging

The Amount of Entry Fee ... £ ... received by me, **13/10 1875**  
 Special ... £ 2 : 2 : -  
 Certificate (if required) ... £ ...  
 (Travelling Expenses, if any, £ ...)

Committee's Minute  
 Character assigned  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 18  
 Record of No 75 of 14/10/75