

SS & Half-Tide Survey 35277* REPORT of SURVEY for REPAIRS, &c. (Recd 22.9.76)

No. in Reg. Book. **No.**

Survey held at London

Date, first Survey Aug 10th

Last Survey 1875

226 on the S Carnatic Composite

Master Chapman

TONNAGE under Tonnage Deck 758.42

Ditto of Spar Deck, or Awning Deck

Ditto of Poop, or Raised Or. Dk. 108.84

Ditto of Houses on Deck 4.04

Ditto of Forecastle

Gross Tonnage 871.30

Crew Space, as per Rule

Register Tonnage, cut on Beam 871.30

Engine Room

Reg. Tons as St^rmer, cut on Bm.

Built at Sunderland

When built 1867

Owners New Zealand Ship

Port belonging to North Shields

Residence

By whom built Pile

Destined Voyage New Zealand

If Surveyed Afloat or in Dry Dock Dry Dock

Length of Poop 56 ft.

Ditto, Forecastle 31 ft.

Ditto, Raised Quarter Deck 1 ft.

Classed 16A

Years assigned 11.73

Character in Register Book 8/74

Last Survey, No. 35277

Port London

REPAIRS, OR EXAMINATION AS PER RULE

At the present time the keel placed in Dry Dock the bottom sighted, being in the bottom equal to 4 Shakes taken up and cement out out at different parts exposing the keel plates and be bolts & rivets and found good. The cement adhering firmly to the iron and wood. Open beiling betwixt decks. Windlass unhung and Wordinging stripped off. Chain cables hauled on deck & examined 300 fathoms.

She was Yellow Metalled last year as per Report attached

Present Condition of the

Decks	Good	Treenails Bolts	Good	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	and
Planksheers	"	Keelsons	"	Sails	Sufficient
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of <u>3</u> <u>12</u> <u>12</u> <u>12</u>	where
Topsides	"	Ceiling	"	Cables <u>300</u> <u>fathoms</u>	they could
Wales	"	Rudder	"	Hawsers and Warps	be seen
Plank (Bottom) and Counter	"	Copper <u>7</u> <u>Metals</u> When put on <u>1874</u>		Standing & Running Rigging	
Engine Room Skylights		Caulking of			
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	Good		
Scuppers	Good			Cargo and Main Hatchways	Good
Hatches	Good				

General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as classed and Marked S.S. H.T. 1875.

Senhouse Martindale

The Amount of Entry Fee ... £ : : : received by me, 10.5.76

24/9/76 Special ... £ 6 : 6 : : 10.5.76

Certificate (if required) ... £ : : :

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

© 2021

Lloyd's Register Foundation

[3,000—8,075.]

[The Surveyors are requested not to write on or below the space for Committee's Minute.]

2110-19907