

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 35283** Survey held at **LONDON** Date, first Survey **17 Jan** Last Survey **7 Feb** 18**76**
 997 on the **"Michael Angelo"** Master **Esson**
 TONNAGE under Tonnage Deck **1084.56** Built at **Glasgow** When built **1865** MONTH. **2**
 Ditto of Spar Deck, or Awning Deck **88.80** Owners **Lidgett** Port belonging to **LONDON**
 Ditto of Poop **88.80** Residence
 Ditto of Raised Or. Dk. **- 68** By whom built Destined Voyage
 Ditto of Houses on Deck **- 68** If Surveyed Afloat or in Dry Dock **Castles Dry Dock**
 Ditto of Forecasts **- 68**
 Gross Tonnage **1174.04**
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St'mer, cut on Bm.
 Length of Poop **53** ft. Ditto, Forecastle **31** ft. Ditto, Raised Quarter Deck ft. Years assigned. **16** Character in Register Book. **At 10.74**
 Last Survey, No. **34196** Port **LONDON** **S.S. 74 H.T. 74**

REPAIRS, OR EXAMINATION AS PER RULE

Yellow Metal stripped off. Bottoms cleaned down. About 5 strakes of Deck next Waterway renewed on each side from about fore mast to before the poop. Five Beams introduced forward below Hold Beams as pointing Beams, there being slight movement there. Vessel Caulked all over and Re-metalled over felt as before.

Surveyed with port cargo on board.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper	Standing & Running Rigging
Engine Room Skylights	When put on	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	Caulking of	Hatches
Scuppers	Bottom, Deck, & Waterways	

General Observations, Opinion as to Class, &c.

This ship appears in good Condition and eligible to remain as classed.

The Amount of Entry Fee ... £ 3 : : received by me, }
 10/10/76 Special ... £ 2 : 2 : } 11 Feb 1876
 Certificate (if required) ... £ : 5 : }

(Travelling Expenses, if any, £)
 Committee's Minute **15th February 1876**

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LONG 61-0120

Michael Supto

1991



© 2021

Lloyd's Register
Foundation