

REPORT of SURVEY for REPAIRS, &c.

35326

No. in Reg. Book. **No.** Survey held at London Date, first Survey 29 Feb^r Last Survey March 1876

410 on the B^e Point Master _____

TONNAGE under Tonnage Deck	Built at <u>London</u>	When built <u>1848</u>	YEAR. MONTH.
Ditto of Spar Deck, or Awning Deck	Owners <u>Anderson</u>	Port belonging to <u>London</u>	
Ditto of Poop	Residence _____	By whom built _____	Destined Voyage _____
Ditto of Raised Qr. Dk.			
Ditto of Houses on Deck			
Ditto of Forecastle			
Gross Tonnage <u>364</u>			
Crew Space, as per Rule			
Register Tonnage, cut on Beam			
Engine Room			
Reg. Tons as St ^r mer, cut on Bm.			

Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft.

Last Survey, No. 33914 Port London Classed 13 Years assigned 13 Character in Register Book 11

REPAIRS, OR EXAMINATION AS PER RULE

This vessel received some damage to Poop and upper works on her last homeward voyage, which has now been temporarily repaired, and the Topsides Caulked.

This ship is being ballasted and prepared for leaving tomorrow on her voyage to the West Indies.

Written notice has been sent to the Owners that the Half Year Survey is due, and that it is necessary for such survey to be held in order to retain the present character in the Register Book.

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	
Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways
Hatches		

General Observations, Opinion as to Class, &c.

Under the circumstances of ballasting and with dummy in Hold, an examination of the vessel could not be satisfactorily made. The case is therefore submitted for the Committee's consideration.

The Amount of Entry Fee ... £ : : received by me, } Mr. Conydon
 Special ... £ : : 187 }
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)

Committee's Minute 7th March 1876

Character assigned 11 reserved

with to London 28/3/76

Noted as 10/3/76

The Surveyors are requested not to write on or below the space for Committee's Minute.

