

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** 568 on the **"Thamow"** Survey held at **London** Date, first Survey **11 May** Last Survey **19 May 1876** Master _____

Official Number _____ Tonnage under Tonnage Deck _____ Ditto of Spar Deck, or Awning Deck _____ Ditto of Poop _____ Ditto of Raised Qr. Dk. _____ Ditto of Houses on Deck _____ Ditto of Forecastle _____ Gross Tonnage **825** Crew Space, as per Rule _____ Register Tonnage, cut on Beam _____ Engine Room _____ Reg. Tons as St' mer, cut on Bm. _____

Built at **Sunderland** When built **1853** Owners **Plythe & Pells** Port belonging to **London** Residence _____ By whom built _____ Destined Voyage _____ If Surveyed Afloat or in Dry Dock **Repair dry dock**

Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft. Years assigned. **10** Character in Register Book. **A1**

Last Survey, No. **34958** Port **London** Best Low Water _____ 5 _____ 8 75

REPAIRS, OR EXAMINATION AS PER RULE

This ship has been specially surveyed for **At sea second Rule**, and the following repairs found necessary. The greater part of upper deck Clamps and some Ceiling in lower decks on Port side, and part of the Clamps and some Ceiling on Star side to be renewed. The four strakes of lower deck Clamps to be renewed on each side from about two shifts shaft main mast forward. Several iron sick plank in the Wales and Topsides and under the quarters on both sides to be renewed. The outside planking of Poop to be repaired and made good. The Clamps and Ceiling referred to are decayed about the knee fastenings and at some other parts. The owner has declined entering upon the Repairs, and they purpose selling the ship.

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings & Fastenings	Transoms, Pointers, and Crutches	Boats
Lower Decks & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Planksh	Ditto Ditto at other places	Condition, how ascertained
Sheerstrakes	Keelsons	Sails
Topsides	Clamps and Shelves	Anchors No. of
Wales	Ceiling	Cables
Plank (Bottom) and Counter	Rudder	Hawsers and Warps
Engine Room	Copper When put on	Standing & Running Rigging
General Remarks, Opinion as to Class, &c.	Caulking of Bottom, Deck, & Waterways	
	Coal Bunker, Openings, Lids, &c.	
	Scuppers	
	Cargo and Main Hatchways	
	Hatches	

We beg to submit that this vessel in her present condition is not entitled to be classed in the Register Book with the character for which she has now been surveyed.

The Amount of Entry Fee ... £ 3 : 3 : received by me, }
 25/5/76 Special ... £ 3 : 3 : 187 }
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)
 Committee's Minute **26th May 1876**
 Character assigned **Exchange Character with black Mark**
 J. H. Bennett
 Surveyor to Lloyd's Register of British and Foreign Shipping
 Let to owner 27/5/76
 Letter to Shields Surveyor 28/5/76

(The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (S, 000-1/11/75.)



Shannon



© 2021

Lloyd's Register
Foundation