

35.483
REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at London Date, first Survey 25th Apr^l Last Survey 17th May 1876
846 on the Barque "Medina" Master J. Lindall

Official Number
TONNAGE under Tonnage Deck
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage
Crew Space, as per Rule
Register Tonnage, cut on Beam 358
Engine Room
Reg. Tons as St^rmer, cut on Bm.
Built at Cowes When built 1857
Owners C. C. Sawson & Port belonging to London
Residence Trillick Square
By whom built White Destined Voyage Jamaica
If Surveyed Afloat or in Dry Dock Laurender by dock.

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
Classed 13 Years assigned. 13 Character in Register Book. 10-66
Last Survey, No. 27830 Port London

REPAIRS, OR EXAMINATION AS PER RULE Damage Repairs.
The Owner requested that the damage repairs be now reported, it being his intention to Reclass the Vessel on her return

Repairs- Yellow Metal sheathing removed bottom and keel examined, fore length of Main keel renewed with English Elm, fore length of garboard and next planks above renewed with American Elm, false keel all fore and aft renewed with American Elm, middle line additionally fastened with yellow Metal through bolts, Vessel recaulked from keel to gunwale and the bottom sheathed with yellow Metal over felts

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
General Observations, Opinion as to Class, &c.	Scuppers	Cargo and Main Hatchways
		Hatches

The Amount of Entry Fee ... £ : : received by me, }
Damage Special ... £ 3 : 3 : 187
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £)

Committee's Minute 18

Character assigned

Thos W. Blasell
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register
Foundation

LON661-0237