

No. 35600 Survey held at London Date May 30<sup>th</sup> 1876 35600  
 on the S Thyatira Master McKaz  
 Tonnage 562 Built at Aberdeen When built 1867 8 mo.  
 By whom built Good Owners G Thompson Junr  
 Port belonging to Aberdeen Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 34565 Port of London Classed 17 A ssbn 73  
 (24th June 1875)  
 The present Condition of the  

Decks <u>Good</u>	Treenails <u>Bolts</u>	<u>Good</u>	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	4	Pumps <u>New of Metal</u>
Comings _____	Transoms, Pointers, and Crutches _____	4	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	4	Masts, Yards, &c. <u>sufficient</u>
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	4	Sails <u>new 1300 ft. 2 topmasts</u>
Planksheers _____	Keelsons _____	4	Ancors, No. of <u>3 br. 10 lb</u>
Sheerstrakes _____	Clamps and Shelves _____	4	Cables _____
Topsides _____	Ceiling _____	4	Hawsers and Warps _____
Wales _____	Rudder _____	4	Standing and Running Rigging _____
Plank (Bottom) and Counter _____	Copper <u>3 Metal</u> When put on <u>1875</u>		

 General Observations and Opinion, \_\_\_\_\_  
 Caulking of Bottom, Deck, and Waterways Good

*She is now in an efficient state of repair  
 and entitled to remain as Clasp*

*Senhouse Martineau*

Committee's Minute 21 July 18 76

Character assigned 17 A

24 July 1876  
*Signature of Surveyor*

*JRM*

Certificate (if required).

Lloyd's Register  
 Foundation