

ANNUAL SURVEYS.

33,685

No. in Reg. Book. on the **No.** 101 Survey held at London Date, first Survey Aug 28 Last Survey 1876
 Tonnage 385 Built at Shoreham When built 1872 6M
 By whom built Maz Owners Bullard & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock

J. B. B.

Last Survey, No. 34499 Port of London Classed 11A 3.75
 Present Condition of the
 Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Y.M. When put on 1875
 Engine Room Skylights " Caulking of Patched now
 Coal Bunker, Openings, Lids, &c. " Bottom, Deck, & Waterways Good
 Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as Classed

Committee's Minute 12th September 1876
 Character assigned 11A

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

J. B. B.

No. in Reg. Book. on the **No.** 470 Survey held at London Date, first Survey Aug 23 Last Survey 1876
 Tonnage 865 Built at Sunder When built 1870 6M
 By whom built Stephens Owners Stephens Sons
 Port belonging to Sunder Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock

J. B. B.

Last Survey, No. 7524 Port of Falmouth Classed 17A 4.75
 Present Condition of the
 Decks Good Treenails Bolts Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Y.M. When put on 1875
 Engine Room Skylights " Caulking of Patched now
 Coal Bunkers, Openings, Lids, &c. " Bottom, Deck, & Waterways Good
 Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as Classed

Committee's Minute 12th September 1876
 Character assigned 17A

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Lloyd's Register Foundation